



Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Red	Solid	1	Analyzer.Amplitude A	Left	
1	2	Red	Solid	1	Analyzer.Amplitude B	Right	

TESTING TERMS:1KHz 1W=0dB WORKING TERMS: 2 CH TESTING FREQUENCY:20Hz--20KHz



Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Red	Solid	1	Analyzer.Level B	Left	
1	2	Red	Solid	1	Analyzer.TH+N Ratio B	Right	
1	3	Red	Solid	1	Analyzer.Level A	Left	
TESTING TERMS: WORKING TERMS:6Ω 2CH INPUT SIGNAL:1KHz							



Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Red	Solid	1	FFT.ChB Amplitude	Left	
1	2	Red	Solid	1	FFT.ChA Amplitude	Left	

TESTING TERMS: