



Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Green	Solid	1	Analyzer.Amplitude A	Left	
1	2	Yellow	Solid	1	Analyzer.Amplitude B	Right	

TESTING TERMS:1KHz 1V=0dB WORKING TERMS: 2 CH TESTING FREQUENCY:20Hz--20KHz




Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Green	Solid	1	Analyzer.Amplitude A	Left	
1	2	Yellow	Solid	1	Analyzer.Amplitude B	Right	
TESTING TERMS:1KHz 1v=0dB					WORK TERMS: R&L 2CH		TESTING FREQUENCY:20Hz--10KHz



Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Green	Solid	1	FFT.ChB Amplitude	Left	
1	2	Yellow	Solid	1	FFT.ChA Amplitude	Left	

TESTING TERMS: 1KHz 1V =0dB TESTING FREQUENCY:20Hz--20KHz



Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Green	Solid	1	Analyzer.TH+D+N Ratio A	Left	
1	2	Yellow	Solid	1	Analyzer.TH+D+N Ratio B	Right	
WORK TERMS: R&L 2CH 1V OUT					TESTING FREQUENCY:20Hz--20KHz		